


# THE FRENCH CLOCK



**Here we have a Barrel with several areas that have been damaged. The teeth looked very unsafe and one did break when being corrected. A new Barrel Wheel was cut and all is well with the clock**